## PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No: 205 Date: 04-04-2024

It is Certified that an inspection team headed by Mr. Harendra Kumar Singh, Junior Engineer From Uttarakhand Jal Sansthan, Bazpur inspected the D.A.V. Public School, Beriya Road, Bazpur on 28-03-2024 and found that the D.A.V. Public School, Beriya Road, Bazpur Udham Singh Nagar has safe drinking water facilities for the student and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the Campus as per the norms Prescribed by the central/State/U.T. Govt.

The above valid for a period of 1 Year.

Signature with Seal

कनिष्ठ अभियंता उत्तराखण्ड जन संस्थान

बाजपर (ऊधमसिंह नगर) उत्तराखण्ड

Name : Harendra Kumar Singh

Designation : <u>Junior Engineer</u>

Name & Address

of Department : <u>Uttarakhand Jal Sansthan</u>, Bazpur

To,

D.A.V. Public School,

Beriya Road, Bazpur

(USN) 262401